

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a val	id maintenance pe	rmit. This permit mu	ist be completed	
prior to performing maintenance activit	ies and remain on-	site for the duration	on of the maintenanc	e activity.	
Date of Maintenance: 10-24-16 Reason	for Maintenance:	Routine	Maintena	me e	
Property Address: 105 Lake circle					
Toperty Address: 10 - Toperty	Draparty Idar	tification Number:	7 /4		
Municipality: <u>Baypoot</u> ZIP:550	O Property idei	itilication Number.			
Maintenance Permit No: <u>eLoO13f5070</u> /	Maintainer Name an	d License No. Ron's	s Sewer Service/ L210	3	
Maintenance Performed	Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped	Liquid Level of T	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
Yes No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage: - Maintena	nce Hole 🗌 Other (e	enter authorization co	ode)		
2. Were all covers securely replaced? Yes	□No				
3. Is there evidence of tank leakage from a sequevidence of damaged, cracked, or structure	ptic, holding, pretr ally unsound main	eatment or pump tenance hole cove	tank below the opera rs?	ting depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes TNo	☐ Yes No	☐ Yes No		
Septic/Holding Tank #2	☐ Yes No	☐ Yes ¶No	☐ Yes No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	d?				
Tank #1 1000 gal Tank #2 1000	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information: List any troubleshooting	— g, minor repairs co	nducted, tank safe	ety concerns, or other	r concerns.	
2					
6. Location of septage disposal:					