

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit m	ust be completed	
prior to perfor	ming maintenance activit	ies and remain on	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:	10-27-16 Reason	for Maintenance:	Koutine	Mainter	rance	
Property Address: <u>\</u>	188 47th St	. N. F	roperty Owner's Na	ame: Tim Ga	mboni	
Municipality: St	Mwater ZIESO	82 Property Ider	ntification Number:			
Maintenance Permit No	: 15647 p50106 M	Maintainer Name ar	d License No. Ron'	s Sewer Service/ L210)3	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
	no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers see3. Is there evidence of	curely replaced? A Yes of tank leakage from a sep ged, cracked, or structur	□ No otic, holding, pretr	eatment or pump	tank below the oper	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ♣No	☐ Yes TNo	☐ Yes ♠ No		
	Septic/Holding Tank #2	☐ Yes ♣TNo	☐ Yes No	☐ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ♣YNo	☐ Yes No	☐ Yes No		
4. How many gallons	of septage were removed	?				
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal						
	: List any troubleshooting				r concerns.	
6. Location of septage	disposal:					