



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the

prior to performing			1.		
Date of Maintenance: 11/2	Z8/17 Reas	son for Maintenance	Markeranou	fant of	
Property Address: 22.75	50 Imperial A	ven	Property Owner's	Name: Tim Brock	men
Municipality: Forest Lake		Property lo			
Maintenance Permit No:	1006229934	_ Maintainer Name	and License No. 0	150n's Sewer	Servia #211
Maintenance P	erjorned	Tank We	işürément (must b	e completed if tank	s NOT pumped)
Tank(s) Pumped  Sludge and scum measured		11 '	Tank in	}	,
			Sludge Level in Tank in Scum Level in Tank in		
Do tanks need to be pu				Level X 10	
☐ Yes ☐ No (if no provide measurements)		(s)    = % Studge & St	tum 18	anks must be pumpe	d if 25% or greater
Were all covers securely	septage: Mainte	r 🗆 No			
	y replaced? 🏻 Ye k leakage from a s cracked, or structi	eptic, holding, pret urally unsound mair			erating depth or
Is there evidence of tan evidence of damaged,	y replaced? Yek k leakage from a s cracked, or structe Tank	eptic, holding, pret urally unsound main Leaking Out	Leaking In	Cover Damage	erating depth or
Is there evidence of tan evidence of damaged,	y replaced? 🏻 Ye k leakage from a s cracked, or structi	eptic, holding, pret urally unsound mair			erating depth or
Is there evidence of tan evidence of damaged,	y replaced? Yek k leakage from a s cracked, or structe Tank	eptic, holding, pret urally unsound main Leaking Out	Leaking In	Cover Damage	erating depth or
Is there evidence of tan evidence of damaged, of Seption	y replaced? Yeak leakage from a scracked, or structor Tank	eptic, holding, preturally unsound main Leaking Out	Leaking In  Yes No	Cover Damage  ☐ Yes ♠No	erating depth or
Seption Septio	y replaced? Ye k leakage from a scracked, or structe  Tank  c/Holding Tank #1  c/Holding Tank #2	eptic, holding, preturally unsound main  Leaking Out  Yes No  Yes No	Leaking In  Yes & No  Yes No	Cover Damage  Yes No Yes No	erating depth or
Seption	replaced? Yeak leakage from a scracked, or structor Tank  c/Holding Tank #1  c/Holding Tank #2  eatment Tank  Tank  Tank  Tank	eptic, holding, preturally unsound main  Leaking Out  Yes No Yes No Yes No Yes No Yes No Res No Res Res	Leaking In  Yes No Yes No Yes No Yes No Yes No	Cover Damage  Yes No Yes No Yes No Yes No	gal