

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be o	ompleted in its entirety	to constitute a va	id maintenance pe	ermit. This permit m	ust be completed	
<u>prior</u> to perforn	ning maintenance activit	ies and remain on	site for the durati	on of the maintenance	ce activity.	
Date of Maintenance:	0-6-16 Reason	for Maintenance:	KPa M	acht		
CVT	OI with si	T 61	100	tak M	thick	
Property Address: 7	01 1901131	-70	roperty Owner's Na	ame: <u>100</u> (114	19/93	
Municipality:	IT LK ZIP: 550		ntification Number:			
Maintenance Permit No	105844590 M	Maintainer Name ar	d License No. $\underline{S_{M}}$	rilies Sewer	Servicea	
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
V)	o provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintena	nce Hole 🗌 Other (6	enter authorization co	ode)		
	urely replaced? Yes				-	
3. Is there evidence of	f tank leakage from a sep ged, cracked, or structur	tic, holding, pretr	eatment or pump tenance hole cove	tank below the operars?	ating depth or	
-	Tank	Leaking Out	Leaking In	Cover Damage		
-	Septic/Holding Tank #1	☐ Yes No	☐ Yes PNo	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes □ No	☐ Yes ♠No	☐ Yes ☑ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	\square Yes \square No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed? Tank #1 (000) gal Tank #2 (000) gal Pretreatment tank gal Pump Tank gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
5. 5.1.6. m.s.m.a.i.e.m. 2.5. m.y, 11.5.2.6.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1.1						
		,				
6. Location of septage	11 10 11	/ / ,	1 and	Angli		