

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a vai	id maintenance pe	ermit. This permit m	ust be completed
<u>prior</u> to perfor	ming maintenance activit	ies and remain on	site for the durati	on of the maintenan	ce activity.
Date of Maintenance:	10/5/16 Reason	for Maintenance:	R.	a maint	7
Property Address: Q_{i}	328 Neal G	Ave. Nº P	roperty Owner's Na	ame: Mary	Petrisko
	nuxter ZIP: 550			7	·
					120
Maintenance Permit No	D: <u>T6454C4588</u>	maintainer Name an	a License No.	milles at	010
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)
. /			ank in	Essentia y 15 of Control of Figure 10 and the	
Tank(s) Pumped	oasurod			Scum Level in Tank_	in
Sludge and scum measured Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or great					f 25% or greater
	A-/				
1. Access used to rem	nove septage: Maintena	ince Hole ☐ Other (€	enter authorization co	ode)	
2. Were all covers securely replaced? 🔯 Yes 🗆 No					
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes X No	☐ Yes 🏹 No	
			/ 1	/ \	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No	/	/ V	
	2 2 250 200 1 3 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons Tank #1 (25()	Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal
Tank #1 1250	Pretreatment Tank Pump Tank of septage were removed	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatmen	Yes No Yes No Yes No tankg	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Horizontal Pump Tank	
Tank #1 1250	Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatmen	Yes No Yes No Yes No tankg	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Horizontal Pump Tank	
Tank #1 1250	Pretreatment Tank Pump Tank of septage were removed gal Tank #2	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ gal Pretreatmen	Yes No Yes No Yes No tank g	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Horizontal Pump Tank	