

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance: 10-22-16 Reason for Maintenance: RC5 Mark						
12105 M						
Property Address: S195 Manning Tri N Property Owner's Name: Cindy Curren						
Municipality: 57/	water ZIP:550	Property Ide	ntification Number:			
VX77711VX01 $C + C + C + M/50$						
Maintenance Permit No	:// <i>0/3/210//</i> N	Maintainer Name a	ild Elcelise 100 M.	HEZZEWAZ	A VICEA SE O	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no	o provide measurements)	= % Sludge & Sc	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Access used to remove septage:</li></ol>						
-	Tank	Leaking Out	Leaking In	Cover Damage	_	
-	Septic/Holding Tank #1	☐ Yes 🖺 No	☐ Yes ☐ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?						
Tank #1 / 2001	gal Tank #2	gal Pretreatmer	it tank ga	al Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
9			1 /	1		
6. Location of septage disposal: wash ( ) and HEDI						
				(1)		