

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
<u>prior</u> to perfor	ming maintenance activi	ties and remain on	site for the durat	ion of the maintenan	ce activity.	
Date of Maintenance:	10-27-16 Reason	n for Maintenance: _				
Property Address: 21859 OLD FIBCO Property Owner's Name: BCHY Janu						
				•		
Municipality: WASH ZIP: 55073 Property Identification Number:						
Maintenance Permit N	0: 00087 V4901	Maintainer Name an	d License No. $\sum_{\mathbf{r}}$	nilies a	498	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks l	NOT pumped)	
Tank(s) Pumped		Liquid Level of 7	Liquid Level of Tank in			
Sludge and scum measured  Sludge Level in Tank in Scum Level in Tank in					in	
Do tanks need to be pumped?   Sludge + Scum / Liquid Level X 100						
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					if 25% or greater	
<ol> <li>Access used to remove septage: Maintenance Hole Other (enter authorization code) Pre 1978</li> <li>Were all covers securely replaced? Yes No</li> <li>Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ol>						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🏿 No	☐ Yes ဩ No	☐ Yes 🏿 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes 🏿 No	☐ Yes ☐ No	☐ Yes ☒ No		
4. How many gallons	of septage were remove	d?				
Tank #1 /000 gal Tank #2 gal Pretreatment tank gal Pump Tank 350 gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
*						