## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

	ompleted in its entirety to	constituto a valid	d maintenance per	mit. This permit mu	st be completed
This section must be c	ompleted in its entirety to ning maintenance activitie	s and romain on-s	ite for the duratio	n of the maintenance	e activity.
<u>prior</u> to perform			Danie	1-1	
Date of Maintenance: <u>/</u>	1-10-16 Reason fo	or Maintenance:	109 10	111-	1.1
Property Address: 7	56 128th ST	Pr Pr	operty Owner's Na	me: Pam Th	elgeson
Municipality: Hu	60 ZIP: 550	Property Ident	tification Number:		
	1 55575312	— sintainar Nama and	d License No. Smili	ie's Sewer Service/L2	428
Maintenance Permit No	: 0.5-2) (G) - 1 CM	anitamer Name and	a Electise No. Shirt		
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1 Access used to rem	ove septage: Maintenan	ce Hole 🗌 Other (e	nter authorization co	de)	
	curely replaced? Yes				
2. Were all covers sec	of tank leakage from a sept	ic holding, pretr	eatment or pump	tank below the opera	ating depth or
evidence of dama	ged, cracked, or structura	ally unsound main	tenance hole cove	rs?	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ☐No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes No	☐ Yes No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 / h/) (	gal Tank #2 / () / (	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	: List any troubleshooting	– , minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.
		1	/ /	1	
6. Location of septag	e disposal: Masi	2 60	Land.	TAPLY	
				Martin Ma	ON A BOSTON BOSTON

RECEIVED

NOV 16 2016