

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be co	ompleted in its entirety to	o constitute a vali	d maintenance per	mit. This permit mu	st be completed
prior to perform	ing maintenance activitie	s and remain on-	site for the duratio	on of the maintenance	e activity.
Date of Maintenance:	7/8/16 Reason for 1962 HILL T.R. M	or Maintenance: _	Routine		
Property Address: #	7962 HILL TR. N	<i>J</i> . Pr	operty Owner's Na	me: THOMAS &	SURNS
	ELMO ZIP: 5508				
Maintenance Permit No:	: <u>r8695a3472</u> M	aintainer Name and	a License No. Meyer	Sewel Servicer E713	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers sec	ove septage: Maintenan urely replaced? Yes [f tank leakage from a sep ged, cracked, or structura	\square No tic, holding, pretr	eatment or pump	tank below the opera	ting depth or
_	Tank	Leaking Out	Leaking In	Cover Damage	
-	Septic/Holding Tank #1	☐ Yes 🖾 No	☐ Yes ऒNo	☐ Yes 闷No	
	Septic/Holding Tank #2	☐ Yes ☑ No	☐ Yes ⊠No	☐ Yes 风No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 /5()() gal Tank #2 /0() gal Pretreatment tank gal Pump Tank					gal
5. Other information:	List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.