

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed | | | | | |
|--|-------------------------|--|--------------------|--------------|------|
| prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. | | | | | |
| Date of Maintenance: 1/11/16 Reason for Maintenance: Routine | | | | | |
| Property Address: <u>/</u> 4 | 1977 18th S | Et. n | roperty Owner's Na | me: Orin 🗸 | Janl |
| Nest of | a a a a a a a | | | | |
| Municipality: | | <u> 第)</u> Property Iden | | | |
| Maintenance Permit No: X/605b/594 Maintainer Name and License No. Meyer Sewer Service/ L915 | | | | | |
| | | | | | |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank in | | | |
| Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if no provide measurements) | | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 1. Access used to remove septage: Maintenance Hole Other (enter authorization code) | | | | | |
| 2. Were all covers securely replaced? Yes No | | | | | |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or | | | | | |
| evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes 🎝 No | ☐ Yes ☐ No | ☐ Yes No | |
| | Septic/Holding Tank #2 | ☐ Yes 🔊 No | ☐ Yes No | ☐ Yes ANo | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| 4. How many gallons | of septage were removed | ? | | | |
| Tank #1 1,756 | gal Tank #2 \ | _gal Pretreatmen | t tank g | al Pump Tank | gal |
| Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal 5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns. | | | | | |
| | | | | | |
| | · | | A | | |
| 6. Location of septage disposal: WTY Sand | | | | | |