

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| This section must be | completed in its entirety to | o constitute a val | id maintenance pe | rmit. This permit m | ust be completed |
|--|---|--|----------------------|----------------------|------------------|
| prior to perfor | ming maintenance activitie | es and remain on- | site for the duratio | on of the maintenan | ce activity. |
| Date of Maintenance: | 7/35/16 Reason fo | or Maintenance: _ | ROUTINE | | ~ |
| Property Address: | 511 NEAL AVE | <u> S</u> P | roperty Owner's Na | me: MAXINE | IVERSON |
| Municipality: WEST | LAKELAND ZIP: 5502 | 32 Property Iden | tification Number: | | |
| Maintenance Permit No | D: 12715g 3478 M | aintainer Name an | d License No. Meye | r Sewer Service/ L91 | 5 |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| ▼ Tank(s) Pumped | | Liquid Level of Tank in | | | |
| Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if no provide measurements) | | = % Sludge & Scum Tanks must be pumped if 25% or greater | | | |
| 2. Were all covers sec3. Is there evidence of | nove septage: Maintenand curely replaced? Yes C of tank leakage from a sept ged, cracked, or structura | □No ic, holding, pretr | eatment or pump t | ank below the oper | ating depth or |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes X No | ☐ Yes No | ☐ Yes ☐ No | |
| | Septic/Holding Tank #2 | ☐ Yes No | ☐ Yes No | ☐ Yes No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | of septage were removed? | | | | |
| Tank #1) 500 gal Tank #2 gal Pretreatment tank gal Pump Tank gal | | | | | |
| 5. Other information | : List any troubleshooting, | minor repairs co | nducted, tank safe | ty concerns, or oth | er concerns. |
| | <u> </u> | | | | |
| 7. | - | 0 | (X) | | |
| 6. Location of septage | e disposal: | DTT 51 | (Tak) | | |