

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.						
Date of Maintenance: 1/26/16 Reason for Maintenance: Routine						
Property Address: 4902 Principle aren. Property Owner's Name: Steve Kempenick						
Municipality: Baytown Day IP: 5533 Property Identification Number:						
	: e7418u3486				5	
			ALL	Company of the Compan	or the company of the	
Maintenance Performed			Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		_	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Ta				nks must be pumped i	f 25% or greater	
 Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes No	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes INo	☐ Yes TNo	☐ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?						
Tank #1 gal Tank #2 \ gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
6. Location of septage disposal: St. Jan.						