

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to perform	ning maintenance activiti	es and remain on-	site for the duration	on of the maintenan	ce activity.
Date of Maintenance:	7/27/16 Reason 1	for Maintenance:	Routine)		
Property Address: 14	404 7th St.	Jane S P	roperty Owner's Na	me: Archie 1	Hazzard)
Municipality:	reland ZIP:550.	43 Property Iden	tification Number:		_
Maintenance Permit No: ml6463493 Maintainer Name and License No. Meyer Sewer Service/ L915					
Maintenar	ce Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)
▼ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if				f 25% or greater
 Access used to remove septage: Admintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes 🕱 No	☐ Yes ☒No	☐ Yes ⊠No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 /200	_ gal Tank #2	gal Pretreatmen	tankg	al Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
S	-				я
6. Location of septage disposal:					