

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety					
<u>prior</u> to perfor	ming maintenance activit	ies and remain on-	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:	7/27/16 Reason	for Maintenance: _	Routine)		1	
Property Address:	59 Julep a	well. P	roperty Owner's Na	ame: Nonna Co	mundson	
Municipality:	e Elmo IP: 55	7/4/3 Property Iden	tification Number:			
	•					
Maintenance Permit No	:X8762F3493	maintainer name an	d License No. Meye	er sewer service? Ext		
Maintenance Performed		Tank Meas	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in 7	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater					f 25% or greater	
	nove septage: X Maintena		enter authorization co	ode)		
2. Were all covers securely replaced? $\cancel{\mathbb{X}}$ Yes \square No						
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes XNo	☐ Yes ☑ No	☐ Yes 🖾No		
	Septic/Holding Tank #2	☐ Yes 🕅 No	☐ Yes No	☐ Yes ☑No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were remove	d?				
Tank #1 / gal Tank #2 / gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
		±				
					*	
6. Location of septage	e disposal:					