

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a val	id maintenance pe	rmit. This permit m	ust be completed	
prior to perform	ming maintenance activit	ies and remain on-	site for the duration	on of the maintenand	ce activity.	
Date of Maintenance:	7/28 Reason	for Maintenance: _	Routine			
Property Address:	085 Quentin	ans S P	roperty Owner's Na	ame: Peace G	Bailers	
0	_ ,			000	J	
	roix Beach IP: 550			er er	<del></del>	
Maintenance Permit No	:: <u>09205/3498</u> 1	Maintainer Name an	d License No. Meye	er Sewer Service/ L915	5	
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)	
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintena	nce Hole 🗌 Other (6	enter authorization co	ode)		
2. Were all covers sec	curely replaced? Yes	□No				
3. Is there evidence of	f tank leakage from a sep ged, cracked, or structur	otic, holding, pretr	eatment or pump tenance hole cove	tank below the operars?	ating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes Tho	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	1?				
Tank #1 156			t tankg	al Pump Tank	gal	
	List any troubleshooting	_ ,, minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.	
-						
		1	$\overline{}$		9	
6. Location of septage	disposal:	NTP St.	Pour			