

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	This section mus	This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be complete					
	prior to pe	prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
	Date of Maintenar	Date of Maintenance: 11-30-16 Reason for Maintenance: 5m					
	Property Address:	Property Address: 4530 332nd Struggle Property Owner's Name: LAOSemple VIPAS					
	Municipality:						
	Maintenance Permit No: 2569 a 5299 Maintainer Name and License No. OSST - # 200						
	VS 27 7 37 31 31 31 31 31 31 31 31 31 31 31 31 31	334 14 12		and Electise No. C	7551 - #6	X110	
	All A Collis	dalije Vicinijase (j. S	A. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	Alica de Colon	ne teorio Herre HT X	ie akang by M	
	Tank(s) Pumpeo	d	Liquid Level o	f Tank i	'n		
	☐ Sludge and scum		Sludge Level i	Tank i	n Scum Level in Ta	nkin	
	Sludge and scum measured Do tanks need to be pumped? Sludge Level in Tank in Scum Level in Tank in Sludge + Scum / Liquid Level X 100						
	☐ Yes ☐ No (if no provide measuremen	its) = % Sludge & S	cum T	anks must be pumpe	ed if 25% or greater	
(6)	1. Access used to re	emove septage: Mainte				•	
1. Access used to remove septage: Maintenance Hole Other (enter authorization code) 2. Were all covers securely replaced? Yes AND DEMO, filled in without could							
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked or structurally uncound maintains.						cover	
	evidence of dan	naged, cracked, or struct	eptic, notaing, pret urally unsound mair	reatment or pump Itenance hole covi	tank below the op	erating depth or	
		Tank	Leaking Out			-	
		Septic/Holding Tank #1		Leaking In	Cover Damage		
			Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
		Septic/Holding Tank #2	☐ Yes ☐ No	Yes No	☐ Yes ☐ No		
		Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No		
		Pump Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
4.	How many gallons	of septage were removed	d?				
	Tank #1 ((())	gal Tank #2	gal Pretreatment	tank ga	l Pump Tank	ani	
5.	Other information:	List any troubleshooting	— , minor repairs cond	ducted, tank safet	V concerns, or other	gal	
6. 1			MALLA	2)	- 1-11		
	ocation of septage	disposal:) wish				
	ocation of septage o	disposal:	on a	vande	ronse	A,	