

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	e completed in its entiret	v to constitute a v	alid maintenance			
prior to perf	oe completed in its entiret	ities and remain	and maintenance	permit. This permit	must be completed	
Data of Main	orming maintenance activ	icies and remain o	n-site for the dura	ation of the maintena	ince activity.	
Date of Maintenance	e: 10-31-15 Reaso	n for Maintenance:	Routine	/		
Property Address: 1	1165 Penfiel	id Aven	Property Owner's	Name: Rob	LOP	
Municipality:	Marter ZIP:133	Property Id	entification Numbe	r:		
Maintenance Permit	No: C 2000 C 0010	Maintainen				
	No: F3077F5047	Maintainer Name a	and License No. Pi	nky's Environmental S	ewer Service/L1673	
Maintenance Performed		Tank Mea	Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		The second secon	Liquid Level of Tank in			
☐ Sludge and scum measured		11	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (it	no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
					or greater	
1. Access used to re	move septage: Maintena	ance Hole 🖊 Other (enter authorization o	code)		
2. Were all covers se	ecurely replaced? Yes	□No				
3. Is there evidence	of tank leakage from a sep	ptic, holding, pret	reatment or pump	tank below the oper	rating denth or	
evidence of dam	aged, cracked, or structur	ally unsound mair	tenance hole cove	ers?	acing depth of	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ZNo	☐ Yes ✓ No	☐ Yes ☐ No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were removed	?	7,77			
Tank #1 1000 gal Tank #2 gal Pretreatment tank				al Pump Tank	gal	
5. Other information	: List any troubleshooting,	, minor repairs co	nducted, tank safe	ety concerns or othe	r concerns	
Munhap u	nder Side walk a	ul linkcape	Edains	of concerns, or other	Concerns.	
-			, ,			
6. Location of septage	e disposal:					