

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

**GOVERNMENT CENTER** 

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be com	pleted in its entirety	to constitute a v	alid maintenance p	ermit. This permit	must be completed	
<u>prior</u> to performing	maintenance activit	ies and remain o	n-site for the durat	tion of the maintena	nce activity.	
Date of Maintenance: 10	S-16 Reason	for Maintenance:	Budking,	mainline	problem	
Property Address: 10010	5 60th St	N	Property Owner's N	lame: Penfit	eld Inc	
Municipality: Stille	ates ZIP: 550	Property Ide	entification Number	:		
Maintenance Permit No:				The state of the s	ewer Service/L1673	
/ Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if no provide measurements)		II .	= % Sludge & Scum Tanks must be pumped if 25% or greater			
Were all covers securely Is there evidence of tan evidence of damaged,	k leakage from a sep	tic, holding, pret	reatment or pump ntenance hole cove	tank below the operers?	rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
Septi	c/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septi	c/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretr	eatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pum	o Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of se	otage were removed?	•	n n			
Tank #11 500 gal	gal Pretreatmer	t tankg	al Pump Tank	gal		
5. Other information: List					er concerns.	
	4	,				
6. Location of septage dispo	osal: Style					