106



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a v	alid maintenance p	permit. This permit n	nust be completed	
prior to performing maintenance activity	ties and remain o	n-site for the dura	tion of the maintenan	ice activity.	
Date of Maintenance: 10-21-16 Reason					
Property Address: 16560 100 St	<u> </u>	Property Owner's N	lame: Dana 1	noclson	
Municipality: Lake Cend ZIP: 30	43 Property Ide	entification Number	:		
Maintenance Permit No: 1300e 41007				wer Service/L1673	
Maintenance Performed	Tank Mea	surement (must be	completed if tanks N	NOT pumped)	
Tank(s) Pumped	Liquid Level of Tank in				
☐ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a seperate evidence of damaged, cracked, or structure. 	otic, holding, pret	reatment or pump ntenance hole cove	tank below the opera	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	🕻 Yes 🙇 No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	Yes 🗆 No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed	?				
Tank #1 300 gal Tank #2 200	gal Pretreatmen		al Pump Tank	gal	
5. Other information: List any troubleshooting, Pearly old System, no ma	minor repairs co	nducted, tank safe	ty concerns, or other	concerns.	
6. Location of septage disposal:					