

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entiret	y to constitute a val	id maintenance pe	ermit. This permit m	ust be complete	
prior to performing maintenance activ			on of the maintenanc	ce activity.	
Date of Maintenance: 12-16-16 Reason	on for Maintenance: _	Routine			
Property Address: 15855 240 5			ame: John a Ki	is 10mnit	
Municipality: SignAba ZIP: 35				<del></del>	
Maintenance Permit No: g 2533 u 5427	Maintainer Name an	d License No. Smi	lie's Sewer Service/L2	2428	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks N	IOT pumped)	
Tank(s) Pumped	Liquid Level of T	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in 7	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum _	Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurement	nts) = % Sludge & Scum Tanks must be pumped if 25% or greater				
<ol> <li>Access used to remove septage: Mainte</li> <li>Were all covers securely replaced? Yes</li> <li>Is there evidence of tank leakage from a secure of tank leakage from a</li></ol>	s 🗆 No			ating depth or	
evidence of damaged, cracked, or struct	urally unsound main	tenance hole cove	ers?		
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes 🏻 No	☐ Yes ♠No	☐ Yes ☒ No		
Septic/Holding Tank #2	☐ Yes 🏿 No	☐ Yes 🖾 No	☐ Yes 🔀 No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were remov	ed?				
Tank #1 1000 gal Tank #2 1000		t tank§	gal Pump Tank	gal	
5. Other information: List any troubleshoot	ng, minor repairs co	nducted, tank saf	ety concerns, or othe	er concerns.	
6. Location of septage disposal:	d applied				