

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET.NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a vali	d maintenance pe	rmit. This permit mu	st be complete
<u>prior</u> to perfor Date of Maintenance: _	ming maintenance activiti	es and remain on-	site for the duration	on of the maintenance	e activity.
Property Address: 14	663 Manniha	to A P	roperty Owner's Na	me: Kont V	pelker
1111	19	XX		•	7. (
Municipality:	water ZIP:550	(Property Iden	tification Number:		_
Maintenance Permit No	:L7228y58	aintainer Name an	d License No. Smil	ie's Sewer Service/L24	28
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	nove septage: Maintenai	nce Hole 🗌 Other (e	nter authorization co	ode)	
2. Were all covers see	curely replaced? Yes	□No			
3. Is there evidence of	of tank leakage from a sep aged, cracked, or structur	tic, holding, pretr	eatment or pump enance hole cove	tank below the opera rs?	ting depth or
	Tank	Leaking Out	Leaking In,	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐No	☐ Yes ☑ No	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐No	☐ Yes ☐No	☐ Yes ☐ Nø	
4. How many gallons	of septage were removed	?		111	(1)
Tank #1 ///	/ gal Tank #2	gal Pretreatment	tankg	al Pump Tank 70	gal
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank safe	ety concerns, or other	concerns.
1		,		1	
6. Location of septage	e disposal: Was	h Co	Cana	1 /104	de
			/	//	