

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance pe	ermit. This permit m	ust be completed
<u>prior</u> to perfor	ming maintenance activiti	es and remain onِ	site for the durati	on of the maintenance	ce activity.
Date of Maintenance:	12-20 Reason 1	for Maintepance: _	Kea M	ain	
Property Address:	633 3474 57	N P	roperty Owner's Na	ame: Animal	Iny
Municipality: Lake	Elmo ZIP: 550	942Property Ider	ntification Number:		
Maintenance Permit N	~ 「 」 「 」 「 「 」 「 「 「			lie's Sewer Service/L2	428
Manifectanee remiters		ame mane an			
. / Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to ren	nove septage: AMaintenan	ce Hole 🗌 Other (e	enter authorization co	ode)	
2. Were all covers see	curely replaced? 4Yes	□No		·	
3. Is there evidence of	of tank leakage from a sep ged, cracked, or structura	tic, holding, pretr			ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	□ Yes ØNo	☐ Yes ZiNo	☐ Yes ☐No	
	Septic/Holding Tank #2	☐ Yes 🗖 No	□ Yes 🖟 No	☐ Yes 🗖 No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?				
Tank #1 /5(C)	gal Tank #2 500	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.
			/ /	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
	1		/		