

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety	to constitute a	alid maintenance p	ermit. This permit	must be completed
<u>prior</u> to perfe	orming maintenance activit	ies and remain o	n-site for the dura	tion of the maintena	nce activity.
Date of Maintenance	: <u>10-17-16</u> Reason	for Maintenance:	Regula M	aintenance	
Property Address:	1150 Joselyn To). N	Property Owner's N	lame: Steve 1	cene
Municipality: 51	Luiter ZIP: 5500	Property Id	entification Number	:	
Maintenance Permit I	No: 5854444485 M	Naintainer Name a	and License No. O	3ST - 7211	D
/ / / / hamles	inite Penthanes () - = 5	18117.119	SUKSIAPOLI JUJSE QE	samineren ("hile:	nert pampe he see
Tank(s) Pumped		Liquid Level of	Tank in		
Sludge and scum measured Sludge Level in Tank in Scum Level in Tank in					
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if	no provide measurements)	= % Sludge & So	um Tai	nks must be pumped i	f 25% or greater
1. Access used to rer	move septage: Maintenan	ce Hole 🗌 Other (enter authorization co	ode)	g .
2. Were all covers se	curely replaced? 🟚 Yes 🛭	□No			
3. Is there evidence	of tank leakage from a sept aged, cracked, or structura	ic, holding, pret	The state of the s		ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes / ÔNo	☐ Yes 🏻 No	☐ Yes 🛱 No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?	51			
Tank #1 \\OD gal Tank #2 gal Pretreatment tank gal Pump Tank					gal
	List any troubleshooting, r				concerns.