

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must b	e completed in its entirety	y to constitute a	valid maintenance	permit. This permit	must be completed	
<u>prior</u> to perf	orming maintenance activi	ities and remain o	on-site for the dura	ition of the mainten	ance activity.	
ž.	e: 7Nov 16 Reason					
Property Address: 2	2671 Jellery Ave Nor	th	Property Owner's	Name: Ubyel + Terry	Nelson	
Municipality: Forest	Lake ZIP: 5502	Property Id	entification Numbe	r:		
a a constant and a co	No: <u>19743 w 485</u> 7				10	
ci Mainken	ange Performed	lan Me	sulcero Engliniliss in	rampiete bir tenis	ders sanger 19 - «	
Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to	Sludge + Scum	Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if	= % Sludge & So	= % Sludge & Scum Tanks must be pumped if 25% or greater				
2. Were all covers se 3. Is there evidence	move septage: Maintenan ecurely replaced? Yes of tank leakage from a sep aged, cracked, or structura	□ No etic, holding, pret	reatment or pump	tank below the oper	rating depth or	
evidence of dam	Tank	Leaking Out	Leaking In			
	BOOK AND THE RESERVE AND THE R		THE PERSON NAMED IN COLUMN TWO	Cover Damage		
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☑No	🗀 Yes 🖾 No		
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☒No	☐ Yes ੴNo	☐ Yes ☑No		
4. How many gallons	of septage were removed?					
Tank #1 1500	gal Tank #2 34/	gal Pretreatment	tankga	l Pump Tank	gal	
,	List any troubleshooting,				r concerns.	
***************************************				*		