

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed						
<u>prior</u> to perfor	ming maintenance activit	ies and remain on-	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:	8/3/16 Reason	for Maintenance: _	Routine)		
Property Address:	6706 3RD St	. 77. P	roperty Owner's Na	ame: John	Joung	
Municipality: Lak	eland ZIP: 55	043 Property Ider	tification Number:		_	
	o: <u>t0962z3516</u>			and the second s	15	
Maintena	nce Performed	Tank Meas	urement (must be	completed if tanks	NOT pumped)	
Tank(s) Pumped		Liquid Level of T	Liquid Level of Tank in			
Sludge and scum measured Sludge Level in Tank				Scum Level in Tank	in	
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100						
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater						
 2. Were all covers securely replaced? Yes No 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 						
	Tank	Leaking Out	Leaking In	Cover Damage		
,	Septic/Holding Tank #1	☐ Yes ☒(No	☐ Yes XNo	☐ Yes 🗗 No		
	Septic/Holding Tank #2	☐ Yes No	☐ Yes 🕅 Yo	☐ Yes 🗷 No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?						
Tank #1 1400 gal Tank #2 906 gal Pretreatment tank gal Pump Tank gal						
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.						
6. Location of septage disposal:						