Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	NAME OF TAXABLE PARTY OF TAXABLE PARTY OF TAXABLE PARTY.	The state of the s			and the second s
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
			_	n of the maintenanc	e activity.
Date of Maintenance:	8/12/16 Reason f	for Maintenance: _	Routine	0 - 0	
Property Address: 8	15 Yovak ave	2. 91 . PI	roperty Owner's Na	me: Annie (a	shman
Municipality: Yeste	Lakeland ZIP: 550	82 Property Iden	tification Number:		
Maintenance Permit No	: <u>e5903p3542</u> M	aintainer Name an	d License No. Meye	r Sewer Service/ L915	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintena	nce Hole 🗌 Other (e	enter authorization co	de)	
2. Were all covers sec	curely replaced? Yes	□No			
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes Tho	☐ Yes No	☐ Yes No	
	Septic/Holding Tank #2	☐ Yes (ZÑo	☐ Yes ☑No	☐ Yes No	
P	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 gal Tank #2 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
2			\wedge		
			(<i>)</i>		
6. Location of septage	e disposal: WT	54.19			