Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

| | | | 500 | | A Company of the Comp |
|---|----------------------------|---|-----------------------|----------------------|--|
| This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed | | | | | |
| prior to performing maintenance activities and remain on-site for the duration of the maintenance activity. | | | | | |
| | 8/25/16 Reason f | | | | 01- 11 |
| Property Address: 8 | 271 39th St | M Pr | operty Owner's Na | me: <u>Vennes</u> | Wilkes |
| Municipality. Like | Elmo ZIP: 550 | 4 Property Iden | tification Number: | | |
| Maintenance Permit No | W 5757/3867 M | aintainer Name and | d License No. Meye | r Sewer Service/ L91 | 5 |
| Maintenance Performed | | Tank Measurement (must be completed if tanks NOT pumped) | | | |
| Tank(s) Pumped | | Liquid Level of Tank in | | | |
| Sludge and scum measured | | Sludge Level in Tank in Scum Level in Tank in | | | |
| Do tanks need to be pumped? | | Sludge + Scum / Liquid Level X 100 | | | |
| ☐ Yes ☐ No (if r | no provide measurements) | = % Sludge & Scum Tanks must be pumped if 2,5% or greater | | | |
| | nove septage: Maintenan | | nter authorization co | ode) Stand | Plps |
| 2. Were all covers securely replaced? 🖾 Yes 🗆 No | | | | | |
| 3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? | | | | | |
| | Tank | Leaking Out | Leaking In | Cover Damage | |
| | Septic/Holding Tank #1 | ☐ Yes ♠No | ☐ Yes ÆNo | ☐ Yes ♠No | |
| | Septic/Holding Tank #2 | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pretreatment Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| | Pump Tank | ☐ Yes ☐ No | ☐ Yes ☐ No | ☐ Yes ☐ No | |
| 4. How many gallons | of septage were removed | ? | | | |
| | | | t tankg | al Pump Tank | gal |
| 77 1974 19 | : List any troubleshooting | , minor repairs co | nducted, tank safe | ety concerns, or oth | er concerns. |
| 1965 | м) | | \bigcirc | | |
| 6. Location of septage disposal: | | | | | |