Washington County

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006

Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

the state of the s				and the second s		
This section must be c	ompleted in its entirety	to constitute a vali	d maintenance per	mit. This permit m	ust be completed	
prior to perforn	ning maintenance activiti	ies and remain on-	site for the duration	on of the maintenance	ce activity.	
Date of Maintenance: _	8/29/16 Reason 73 Olene Co	for Maintenance: _	Routine)		
Property Address: <u>/5</u>	73 Olene Co	lue. n. Pi	operty Owner's Na	me: Ed Hara	Heiry	
Municipality: Nest	Tykeland ZIP: 550	43 Property Iden	tification Number:			
Maintenance Permit No	: <u>935/653875</u> N	Maintainer Name an	d License No. <u>Meye</u>	r Sewer Service/ L91	5	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in T	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: 🔀 Maintena	unce Hole 🖎 Other (e	nter authorization co	de) Slar	1910e	
2. Were all covers sec	curely replaced? 🏿 Yes	□No			•	
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?						
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🏿 No	☐ Yes No	☐ Yes No		
	Septic/Holding Tank #2	☐ Yes 汉 No	☐ Yes ANo	□ Yes No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	R	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons	of septage were remove	d?				
Tank #1 \ \ doo gal Tank #2 \ \ \ \ gal Pretreatment tank gal Pump Tank					gal	
5. Other information	: List any troubleshooting	— g, minor repairs co	nducted, tank safe	ety concerns, or othe	er concerns.	
SAID the	ey are mant	role + sta	ndpipe			
			-			
6. Location of septage	e disposal:	Mt8 3	HIVN			