## Washington County

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

					to a firm the second of the late.
This section must be	completed in its entirety to	constitute a vali	d maintenance per	mit. This permit mu	ist be completed
prior to perfor	ming maintenance activitie	s and remain on-s	ite for the duratio	n of the maintenanc	e activity.
Date of Maintenance: _	<u>8/30/16</u> Reason fo	or Maintenance: _	ROUTINE		
Property Address: 3	508 KELVIN AV	<u>IE N</u> Pr	operty Owner's Na	me: ALBERT	LINDER
Municipality: LAKE	ELMO ZIP: 550	42 Property Iden	tification Number:		-
Maintenance Permit N	o: <u>b 3249 j 3884</u> ma	aintainer Name an	d License No. Meye	r Sewer Service/ L915	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
▼ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers se	nove septage:  Maintenand curely replaced?  Yes of tank leakage from a sept aged, cracked, or structura	☐ No tic, holding, pretr	eatment or pump	tank below the opera	
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?	?			
Tall #1 / 1000 gat Tall #2 / 1000 gat Tall #2					gal gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe hoh Cerve	ety concerns, or othe	er concerns.
6. Location of septag	ge disposal:	StR	v/		