Washington 14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730 Subsurface Sewage Treatment System Maintenance P

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

Subsurface Sewage Treatment System Maintenance Permit

	ompleted in its entirety to	o constitute a vaii	u maintenance per	mit. This permit m	ust be completed	
	ning maintenance activitie			n of the maintenand	ce activity.	
Date of Maintenance:	8/31/16 Reason f	or Maintenance: _	ROUTINE			
Property Address: <u>//</u>	440 UPPER 2	2NDST.S. PI	operty Owner's Na		EZIGAN	
Municipality: St.Ce o	DIX BEACH ZIP: 550	/3 Property Iden	tification Number:			
Maintenance Permit No	: <u>U7583v3889</u> M	aintainer Name and	d License No. Meye	r Sewer Service/ L91	5	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
▼ Tank(s) Pumped		Liquid Level of Tank in				
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?			Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to rem	ove septage: Maintenar	ice Hole 🗌 Other (e	nter authorization co	de)		
2. Were all covers sec	curely replaced? 💆 Yes [□No				
3. Is there evidence of	of tank leakage from a sep	tic, holding, pretr	eatment or pump	tank below the oper	rating depth or	
evidence of dama	ged, cracked, or structura	ally unsound main	tenance hole cove	rs?		
evidence of dama	ged, cracked, or structura ————————————————————————————————————	ally unsound main Leaking Out	tenance hole cove Leaking In	rs? Cover Damage		
evidence of dama	ged, cracked, or structura	ally unsound main	tenance hole cove	rs?		
evidence of dama	ged, cracked, or structura Tank	Leaking Out	Leaking In	Cover Damage		
evidence of dama	Tank Septic/Holding Tank #1	Leaking Out Yes No	Leaking In Yes No	Cover Damage See Yes No		
evidence of dama	Tank Septic/Holding Tank #1 Septic/Holding Tank #2	Leaking Out Yes No	Leaking In Yes No	Cover Damage Yes No		
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	Leaking Out Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No		
	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No	gal	
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	
4. How many gallons Tank #1	Tank Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank of septage were removed	Leaking Out Yes No Yes No Yes No Yes No Yes No	Leaking In Yes No Yes No Yes No Yes No	Cover Damage Yes No Yes No Yes No Yes No	gal	