

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a val	id maintenance pe	ermit. This permit n	nust be completed
prior to performing maintenance activit	ies and remain on	site for the durati	on of the maintenar	ice activity.
Date of Maintenance: 13/26/16 Reason	for Maintenance: _	Regi	maint.	
Property Address: 23744 St. Crois	Talk F	roperty Owner's Na	ame: Chay C	entz
Municipality: Pandia zip:55/	73 Property Idea	ntification Number:		
La contraction of the contractio				2429
Maintenance Permit No: <u>d3058 v5847</u>	maintainer name ar	id License No. Simi	ie's Sewer Service/L	2426
Maintenance Performed	Tank Measurement (must be completed if tanks NOT pumped)			
▼ Tank(s) Pumped	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 2. Were all covers securely replaced? Yes 3. Is there evidence of tank leakage from a selevidence of damaged, cracked, or structure 	otic, holding, preti			rating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes XNo	☐ Yes X No	☐ Yes ☒No	
Septic/Holding Tank #2	☐ Yes X No	☐ Yes XNo	☐ Yes 💢 No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes X No	☐ Yes 🕅 No	☐ Yes XNo	
4. How many gallons of septage were removed	d?	,	/	
Tank #1 1500 gal Tank #2 1000	_ gal Pretreatmer		al Pump Tank <u>3 (</u>	
5. Other information: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or oth	er concerns.
	4 0			
6. Location of septage disposal: $\sqrt{5.000}$.1-A		RECEN	/ D
			DEC 30 2	2016

PUBLIC HEALTH