

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety					
prior to perfor	ming maintenance activit				e activity.	
Date of Maintenance:	12-20-/6 Reason	for Maintenance: _	Routin	૯		
Property Address: <u>9</u> 5	00 235 th St N	P	roperty Owner's Na	ame: John & Ma	argo Morill	
Municipality: Fores	LK ZIP: 5302	Froperty Ider	tification Number:		_	
Maintenance Permit No		— √aintainer Name an	d License No. Smil	ie's Sewer Service/L24	128	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
🕅 Tank(s) Pumped		Liquid Level of Tank in				
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if i	no provide measurements)	= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	curely replaced? 🖄 Yes of tank leakage from a sep aged, cracked, or structur	ptic, holding, pretr	tenance hole cove	ers? 	ting depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Septic/Holding Tank #1	☐ Yes 🌠 No	☐ Yes 🗹 No	☐ Yes 🖼 No		
	Septic/Holding Tank #2	Yes No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
	Pump Tank	☐ Yes 🌠 No	☐ Yes 🎾 No	☐ Yes ௸No		
4. How many gallons	of septage were removed	d?		770		
Tank #1 /000	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank 500	gal	
5. Other information	: List any troubleshooting	g, minor repairs co	nducted, tank safe	ety concerns, or other	r concerns.	
•		4				
6. Location of septag	e disposal: <u>La</u>	nd appli	red	RECEIVI		
				DEC 3 0 201	c	

PUBLIC IIIITH