## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TDD: 651-430-6246 FAX: 651-430-6730

## **SSTS MAINTENANCE REPORT**

Date of Maintena	nce 12-7-15 Reason for	Maintenance:	armec		
Property Address:	1400 12th Ave	Proper	ty Owner's Name:	reg fortor	
Municipality: N	lawfort s	tate MP Zip Code	55055 GEO Cod	e/Property I.D. #:	
What was done to the system?		Tank Measurements (must be completed if tanks NOT pumped)			
<ul> <li>☐ Tank(s) Pumped</li> <li>☐ Sludge and scum measured.</li> <li>Do tanks need to be pumped?</li> <li>☐ Yes</li> <li>☐ No (If no provide measurements)</li> </ul>		Liquid Level of Tanl Total (Sludge + Scu	•	* = % Sludge & Scum*	
1. Access used to remove septage: Maintenance Hole Other (Go to #3 below)  * Tank must be pumped if this value is greater than 25%.					
2. If maintenance	hole was used, were all covers se	ecurely replaced?	Yes No please expla		
Explanation:			18		
	es to allow a Subsurface Sewag and sign the following staten		(SSTS) to be pumped th	rough the maintenance hole, have	
I, (owner's name), refuse to allow the removal of solids and liquids through the maintenance					
hole. I understand that removal of solids and liquids through other access points is not considered maintenance.					
4. Is the tank designed as a leaky tank? example: seepage pit, cesspool, drywell, leaching pit					
Tank#1 Yes No Verificatio Method Used:					
Tank#2 Yes No Verificatio Method Used:					
5. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
•	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes No	☐ Yes ⊀ No	☐ Yes <b>※</b> No	
	Septic/Holding Tank #2	☐ Yes 🔀 No	☐ Yes ►No	Yes No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	Yes No	
6. How many ga	llons of septage were removed	?			
Tank #1 1000 Tank #2 \ \ \ \ O \ O \ Pretreatment Tank			nk Pu	Pump Tank	
7. Other informa	ation: List any troubleshooting	, minor repairs cond	ucted, tank safety conce	rns, or other concerns.	
8. Certification:	I hereby certify as a State of Min and made the observations, or o	directly supervised ot	hers in the performance o	f this job.	
Maintainer's Name: SCHLOMKA SERVICES LLC. Maintainer's Address: 13450 122nd St S, Hastings MN 55033					
Maintainer's License #: 2989 Maintainer's Phone #: 651-459-3718					
	icense #: 2989 Maintain	er's Phone #: 651-45	9-3718		