

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety	to constitute a va	lid maintenance p	ermit. This permit m	ust be completed
<u>prior</u> to perfor	ming maintenance activit	ies and remain on	-site for the durat	tion of the maintenan	ce activity.
	8-10-16 Reason				
Property Address:	7855 44th GL	ct N	Property Owner's N	lame: T. SN	ELL
Municipality: OUKD	ar ZIP: SST	19 Property Ide	ntification Number	:	
Maintenance Permit N	0: <u>(73734K0951</u> pa	Maintainer Name a	nd License No	2989	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
$\square$ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul><li>2. Were all covers sea</li><li>3. is there evidence of</li></ul>	nove septage:	□ No / \ otic, holding, preti	reatment or pump	tank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ⋈ No	☐ Yes ☒No	☐ Yes ⋈ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed	?			
Tank #1 1256 gal Tank #2		gal Pretreatmen	t tank	gal Pump Tank	gal
5. Other information	: List any troubleshooting	, minor repairs co	nducted, tank saf	ety concerns, or othe	r concerns.