

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to	constitute a vali	d maintenance pe	rmit. This permit m	ust be completed
prior to performing maintenance activitie		A	on of the maintenanc	e activity.
Date of Maintenance: 9-7-16 Reason for	or Maintenance: _	Rowin		
Property Address: 1666 5th 5th 5	, Pi	roperty Owner's Na	ame: VCrh Bc	rogren
Municipality: Letterand ZIP: 55043	3 Property Iden	tification Number:		_
Maintenance Permit No: N7149po953 Mi	aintainer Name an	d License No. Z	989 SCHI	onka Sov
Maintenance Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)
Tank(s) Pumped	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Were all covers securely replaced? Yes Is there evidence of tank leakage from a septential evidence of damaged, cracked, or structural 	ic, holding, pretr	eatment or pump tenance hole cove	tank below the operers?	ating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes 欠 No	☐ Yes ☑ No	
Septic/Holding Tank #2	☐ Yes ဩNo	☐ Yes ♠No	☐ Yes ☑No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed				
4. How many gallons of septage were removed:				
Tank #1 $\int OO$ gal Tank #2 $\int OOO$ 5. Other information: List any troubleshooting,	gal Pretreatmen	t tank§		gal gal