

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to perfor	ming maintenance activitie	es and remain on-	site for the duration	on of the maintenan	ce activity.
Date of Maintenance: 9-19-16 Reason for Maintenance: Peg. Mant					
Property Address: 15790 15th St.S. Property Owner's Name: L. RUNK					
Municipality: AFTON ZIP: 00 Property Identification Number:					
7160					
Maintenance Permit No: 17 29050958 Maintainer Name and License No. 2789					
Maintenar	nce Performed	Tank Meas	urement (must be	completed if tanks I	NOT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped? Sludge + Scum / Liquid Level X 100					
☐ Yes ☐ No (if i	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
1. Access used to remove septage: Maintenance Hole Other (enter authorization code) DR-dates - 18					
2. Were all covers securely replaced? 📈 Yes 🗆 No					
3. Is there evidence of tank leakage from a septic, holding, protreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes K No	☐ Yes 🗖 No	☐ Yes ဩNo	
	Septic/Holding Tank #2	☐ Yes \\	Yes No	☐ Yes ऄNo	V .
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 1000 gal Tank #2 1000 gal Pretreatment tank gal Pump Tank gal					
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					
	8				