

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

			· · · · · · · · · · · · · · · · · · ·	1	
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 9-76-16 Reason for Maintenance: Routine					
Property Address: 12288 1315+ 5+ C+ 5 Property Owner's Name: John Klinsher					
Municipality: 124 ZIP: 55033 Property Identification Number:					
Maintenance Permit No: M8177 B0915 Maintainer Name and License No. 2989 Schlomko Schu					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b	Parton.	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if r	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ul> <li>2. Were all covers securely replaced?  Yes □ No</li> <li>3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?</li> </ul>					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes ☑ No	☐ Yes 🖾 No	
	Septic/Holding Tank #2	☐ Yes 🗹 No	☐ Yes 🛣 No	☐ Yes No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 1000			al Pump Tank	gal	
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					