

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be	completed in its entirety t	o constitute a val	id maintenance pe	rmit. This permit m	ust be completed
<u>prior</u> to perfor	ming maintenance activitie	es and remain on-	site for the durati	on of the maintenand	ce activity.
	9/26 Reason f			, ,	
Property Address:	2800 PAILEY	CT. P	roperty Owner's Na	ame: HAPDER	
Municipality: 600	Y NEW ZIP:	Property Ider	tification Number:		_
Maintenance Permit N	0: KS172x0968M	aintainer Name ar	d License No	2989	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence	curely replaced? Yes [of tank leakage from a septaged, cracked, or structura Tank	tic, holding, preti	teatment or pump tenance hole cove Leaking In	tank below the operars? Cover Damage	ating depth or
	Septic/Holding Tank #1	☐ Yes 🏋 No	☐ Yes 🕅 No	☐ Yes 风No	
	Septic/Holding Tank #2	☐ Yes ☒No	☐ Yes ≯No	☐ Yes ☑No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	of septage were removed?	?			
Tank #1 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	gal Tank #2 (OOO	gal Pretreatmen	t tankg	al Pump Tank	gal
5. Other information	: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.