

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 9-29-16 Reason for Maintenance: Rowline					
Property Address:	3700 Norshea	D AVE PI	operty Owner's Nam	e: Robert	cabral
Municipality: A Flor ZIP: Bood Property Identification Number:					
Maintenance Permit No: F711830973 Maintainer Name and License No. 7989 SCNIOMKA SCRV					
Maintenan	ce Performed	Tank Measu	rement (must be co	ompleted if tanks NC	T pumped)
✓ Tank(s) Pumped		Liquid Level of Tank in			
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to b		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or gr					25% or greater
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
•	Tank	Leaking Out	Leaking In	Cover Damage	
,	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes ☐₩o	☐ Yes ☒No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 \500	gal Tank #2	gal Pretreatment	tank gal	Pump Tank	gal
5. Other information:	List any troubleshooting,	minor repairs cor	nducted, tank safety	concerns, or other	concerns.