

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT





Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed					
prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.					
Date of Maintenance: 10/1/16 Reason for Maintenance: 12602M					
Property Address: 11525 1222 St. 5 Property Owner's Name: TCHIDA					
Municipality: DENMAR ZIP: Property Identification Number:					
Maintenance Permit No: 4924750982 Maintainer Name and License No. Scitconky 2489					
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenance Hole Other (enter authorization code) Were all covers securely replaced? Yes No Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers? 					
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes XÌNo	☐ Yes 🗗 No	☐ Yes 🕅 No	
	Septic/Holding Tank #2	☐ Yes No	☐ Yes No	☐ Yes ☐No	
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?					
Tank #1 (ひつ gal Tank #2 <u></u> () さい		gal Pretreatmen	t tank!	gal Pump Tank	gal
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.					