

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT **GOVERNMENT CENTER**

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	completed in its entirety to				
prior to perform	ning maintenance activitie	s and remain on	site for the duration	on of the maintenanc	ce activity.
	10/7/16 Reason fo			. 1	
Property Address: 13	180 LYNER	<u>RD</u> F	roperty Owner's Na	ime: Heris	
Municipality: Hoc	O ZIP:	Property Ide	ntification Number:		_
Maintenance Permit No	: 1071210991 Ma	aintainer Name ar	nd License No. <u>564</u>	Workt 298	39
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)			
☑ Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	curely replaced? \(\int\) Yes \(\int\) If tank leakage from a septinged, cracked, or structura	ic, holding, pret	reatment or pump Itenance hole cove	tank below the oper	ating depth or
	Tank	Leaking Out	Leaking In	Cover Damage	
	Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☑ No	
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pretreatment Tank	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No	
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons	Pump Tank of septage were removed?		☐ Yes ☐ No	☐ Yes ☐ No	ć
Tank #1 (SC()	of septage were removed?	gal Pretreatmen	nt tankg	al Pump Tank	gal
Tank #1 (SC()	of septage were removed?	gal Pretreatmen	nt tankg	al Pump Tank	