

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

				ermit. This permit n		
<u>prior</u> to perforn	ning maintenance activit	ies and remain on-	site for the durati	on of the maintenan	ce activity.	
Date of Maintenance:	10-31-16 Reason	for Maintenance: _	Routine			
	177 Kents AVE			ame: Roser	Lerson	
Municipality: Still	water ZIP: G/D	82 Property Iden	tification Number:			
A STATE OF THE STA	: R272751003				MKa Serv	
Maintenance Performed		Tank Measurement (must be completed if tanks NOT pumped)				
▼ Tank(s) Pumped		Liquid Level of T	Liquid Level of Tank in			
Sludge and scum measured		The state of the s	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		_	Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scu	= % Sludge & Scum Tanks must be pumped if 25% or greater			
3. Is there evidence of	urely replaced? X Yes of tank leakage from a se ged, cracked, or structu	ptic, holding, pretr	eatment or pump tenance hole cove	tank below the ope ers?	rating depth or	
	Tank	Leaking Out	Leaking In	Cover Damage		
	Tank Septic/Holding Tank #1	Leaking Out Ves KNo	Leaking In Yes No	Cover Damage ☐ Yes ☒ No		
	Septic/Holding Tank #1	☐ Yes ☒No	☐ Yes ဩ(Ño	☐ Yes ☒ No		
	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☑No	☐ Yes ☐ No	☐ Yes ☒ No		
4. How many gallons	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☑No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☐ No		
Tank #1 \200	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank	☐ Yes ☑No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ Ro d? gal Pretreatmen	☐ Yes ☐ No ☐ tank	☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No	gal	