

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

prior to perform	500 500 E0074			- 6 th	ast be completed
	ing maintenance activitie				ce activity.
	11-1-16 Reason fo				
Property Address:	66 9th 52 N	P	roperty Owner's Nam	ne: Tchurch	svu
Municipality: 10%	EMO ZIP: 5504	7 Property Iden	tification Number:		
				1/20 / 1	LAK, CA
Maintenance Permit No:	K780021009 M	uintainer Name an	d License No.	187 >cr	100000000000000000000000000000000000000
Maintenand	e Performed	Tank Measi	urement (must be co	ompleted if tanks N	(OT pumped)
Tank(s) Pumped		Liquid Level of Tank in			
☐ Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
\square Yes \square No (if no provide measurements)		= % Sludge & Scum Tanks must be pumped if 25% or greater			
2. Were all covers secu	ove septage: Maintenandurely replaced? Yes	□No			ating depth or
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?					
	Tank	Leaking Out	Leaking In	Cover Damage	
<u> </u>	Tank Septic/Holding Tank #1	Leaking Out Yes Mo	Leaking In ☐ Yes ☒ No	Cover Damage Ves No	
S	Septic/Holding Tank #1	☐ Yes ☐ Yo	☐ Yes No	☐ Yes ⊠No	
S	Septic/Holding Tank #1 Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☒No	☐ Yes ☒No	
S F —	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☐ No	☐ Yes ☒No ☐ Yes ☐ No ☐ Yes ☐ No	
4. How many gallons of Tank #1	Septic/Holding Tank #1 Septic/Holding Tank #2 Pretreatment Tank Pump Tank f septage were removed?	Yes No Yes No Yes No Yes No	☐ Yes ☒ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ Yes ☐ No ☐ tankgal	☐ Yes ☒ No ☐ Yes ☐ No	gal