

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its enti	rety to constitute a val	id maintenance p	ermit. This permit	must be completed	
prior to performing maintenance a	ctivities and remain on-	site for the durat	ion of the maintena	ance activity.	
Date of Maintenance: 11-3 Re	eason for Maintenance:	Routine			
Property Address: 2620 boy	AVE N P	roperty Owner's N	lame: <b>BIII</b> An	nunzian	
Municipality: Forest Loke ZIP:	S625 Property Ider	tification Number	•		
Maintenance Permit No: <u>E4954</u> ‡101	Maintainer Name an	d License No. 2	989 Schlom	ka	
Maintenance Performed	Tank Meas	urement (must be	completed if tanks	s NOT pumped)	
Tank(s) Pumped					
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in				
Do tanks need to be pumped?		Sludge + Scum / Liquid Level X 100			
$\square$ Yes $\square$ No (if no provide measurem	ents) = % Sludge & Sci	= % Sludge & Scum Tanks must be pumped if 25% or greater			
<ol> <li>Access used to remove septage: Mai</li> <li>Were all covers securely replaced?</li> <li>Is there evidence of tank leakage from evidence of damaged, cracked, or street</li> </ol>	Yes □ No a septic, holding, pretr	eatment or pump	tank below the op	erating depth or	
Tank	Leaking Out	Leaking In	Cover Damage	_	
Septic/Holding Tank #	1 ☐ Yes ☑No	☐ Yes ☒No	☐ Yes ☐ No		
Septic/Holding Tank #.	2 ☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	<del>-</del>	
4. How many gallons of septage were ren					
Tank #1 \ 75 0 gal Tank #2	gal Pretreatmen	t tank	gal Pump Tank	gal	
5. Other information: List any troublesho	oting, minor repairs co	nducted, tank saf	ety concerns, or ot	her concerns.	