

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

		A STATE OF THE PARTY OF THE PAR		This	and he completed			
This section must be completed in its entirety to constitute a valid maintenance permit. This permit must be completed prior to performing maintenance activities and remain on-site for the duration of the maintenance activity.								
			A	on of the maintena	nce activity.			
Date of Maintenance:	11-6-16 Reason	for Maintenance: _	Routhe					
Property Address: 8737 75th STN Property Owner's Name: Parrick Farell								
Municipality: Shill	JULY ZIP: 5508	2 Property Ider	tification Number:					
Maintenance Permit No: Mosab Mous Maintainer Name and License No. 5 HOMK CEN 289								
	nce Performed		AND AND ADDRESS OF THE STATE OF	completed if tanks				
Tank(s) Pumped		Liquid Level of Tank in						
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in						
Do tanks need to b		Sludge + Scum / Liquid Level X 100						
MODERN COMMISSION COMM	no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater						
 Access used to remove septage:								
	Tank	Leaking Out	Leaking In	Cover Damage	•			
	Septic/Holding Tank #1	☐ Yes ⊠No	☐ Yes 🗹 No	☐ Yes ⊠No	is .			
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No				
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No				
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	-			
4. How many gallons	of septage were removed	?						
Tank #1 500 gal Tank #2		gal Pretreatment tankg		al Pump Tank	gal			
5. Other information: List any troubleshooting, minor repairs conducted, tank safety concerns, or other concerns.								



DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER



14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

	ompleted in its entirety t							
<u>prior</u> to perforn	ning maintenance activiti	es and remain on-	site for the duration	on of the maintenanc	e activity.			
Date of Maintenance:	1-6-16 Reason 1	for Maintenance: _	Routne					
Property Address:	137 75th st	. N P	roperty Owner's Na	No.	Farell			
Municipality: 当心し	JUREN ZIP: SSOS	2 Property Ider	tification Number:	•				
	: MOSap WIOR W				en 1889			
Maintenan	ce Performed	Tank Meas	urement (must be	completed if tanks N	OT pumped)			
Tank(s) Pumped		Liquid Level of Tank in						
Sludge and scum measured		Sludge Level in Tank in Scum Level in Tank in						
Do tanks need to b	e pumped?		Sludge + Scum / Liquid Level X 100					
Yes No (if no provide measurements) = % Sludge & Scum Tanks must be pumped if 25% or greater								
	ove septage: Maintenar		enter authorization co	ode) Pre18				
2. Were all covers securely replaced? ✓ Yes ☐ No								
3. Is there evidence of tank leakage from a septic, holding, pretreatment or pump tank below the operating depth or evidence of damaged, cracked, or structurally unsound maintenance hole covers?								
•	Tank	Leaking Out	Leaking In	Cover Damage				
	Septic/Holding Tank #1	☐ Yes ⋈No	☐ Yes 🖾 No	☐ Yes ☒No				
	Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No				
	Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No				
	Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No				
4. How many gallons	of septage were removed	?						
Tank #1 500	gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal			
5. Other information:	List any troubleshooting	, minor repairs co	nducted, tank safe	ty concerns, or other	r concerns.			