

## DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

## Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a va	alid maintenance	permit. This permit	must be completed	
<u>prior</u> to performing maintenance activit	ies and remain or	n-site for the dur	ation of the maintena	nce activity.	
Date of Maintenance: 11-8-16 Reason	for Maintenance:	Routine			
Property Address: 11133 Pawnee P					
Municipality: Stillwuttu ZIP: 550	Property Ide	entification Numb	er:		
Maintenance Permit No: 03685 j 4942					
Maintenance Performed	Tank Mea	surement (must I	be completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of	Tank i	n		
$\square$ Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
$\square$ Yes $\square$ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater				
1. Access used to remove septage:   Maintenar					
2. Were all covers securely replaced?  Yes	No		-		
3. Is there evidence of tank leakage from a seperite evidence of damaged, cracked, or structuration	tic, holding, preta Ally unsound main	reatment or pum tenance hole co	p tank below the oper vers?	rating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?					
Tank #1 /500 gal Tank #2	gal Pretreatmen	t tank	gal Pump Tank	gal	
5. Other information: List any troubleshooting,	minor repairs co			er concerns.	
manhole under decles	land scaping				
6 Location of south and discount					
6. Location of septage disposal:					