

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

prior to performing maintenance activiti	to constitute a v es and remain o	alid maintenance n-site for the dura	permit. This permit	must be completed
Date of Maintenance: Reason				c uctivity.
Property Address: 13820 23rd StN		Property Owner's	Name: Elton G	unningham
Municipality: Still Doutor ZIP: 30	Property Id	entification Numbe	r:	J
Maintenance Permit No: <u>12448e4981</u> M				ewer Service/L1673
Maintenance Performed	Tank Mea	surement (must b	e completed if tanks	NOT pumped)
Tank(s) Pumped	Liquid Level of	Tank in		
☐ Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Sc	um Ta	anks must be pumped	if 25% or greater
 Access used to remove septage: Maintenance Were all covers securely replaced? Yes Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structural 	No	reatment or nump	tank below the ener	rating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	\square Yes \square No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 /3 00 gal Tank #2	gal Pretreatmen	t tank g	al Pump Tank	gal
5. Other information: List any troubleshooting, refere built in 15, No	ninor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.
6. Location of septage disposal:				