

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

This section must be completed in its entirety	to constitute a v	alid maintenance	permit. This permit	must be completed
<u>prior</u> to performing maintenance activit	ies and remain o	n-site for the dur	ation of the maintena	nce activity
Date of Maintenance: 11-9-16 Reason	for Maintenance:	Routin		
Property Address: 8968 364 St	V	Property Owner's	Name: Enily	Boe
Municipality: Lake Elmo ZIP: 530	YA Property Id	entification Numbe	er:	
Maintenance Permit No: 45366m4959				ewer Service/L1673
Maintenance Performed	Tank Mea	surement (must b	pe completed if tanks	NOT pumped)
✓ Tank(s) Pumped	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Scum Tanks must be pumped if 25% or greater			
 Access used to remove septage: Maintenar Were all covers securely replaced? Yes Is there evidence of tank leakage from a sependence of damaged, cracked, or structural 	□ No tic, holding, pret	reatment or pum	n tank below the oper	ating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes Ø No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes Z No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				
Tank #1 1500 gal Tank #2 1000	gal Pretreatmen	t tank	gal Pump Tank	gal
5. Other information: List any troubleshooting,	minor repairs co	nducted, tank saf	ety concerns, or other	r concerns.
6. Location of septage disposal:				