

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

prior to performing maintenance activity	to constitute a vi ies and remain o	alid maintenance n-site for the dura	permit. This permit to the second the maintena	must be completed nce activity.	
Date of Maintenance: //-28-/6 Reason				,	
Property Address: 995 53rel St			Name: Talo o	255 WIO W	
Municipality: Lake Elmo ZIP:550				HELLOW?	
Maintenance Permit No: 2500/45029 N				 ewer Service/L1673	
Maintenance Performed	Tank Mea	surement (must be	e completed if tanks	NOT pumped)	
Tank(s) Pumped	Liquid Level of	Tank in			
\square Sludge and scum measured	Sludge Level in	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100				
☐ Yes ☐ No (if no provide measurements)	= % Sludge & Sc	um Ta	inks must be pumped	if 25% or greater	
Is there evidence of tank leakage from a sept evidence of damaged, cracked, or structura	ic, holding, pret Ily unsound mair	reatment or pump tenance hole cove	tank below the oper ers?	ating depth or	
Tank	Leaking Out	Leaking In	Cover Damage		
Septic/Holding Tank #1	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
Pump Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No		
4. How many gallons of septage were removed?					
Tank #1 gal Tank #2	gal Pretreatmen	t tankg	al Pump Tank	gal	
5. Other information: List any troubleshooting,	minor repairs co	nducted, tank safe	ety concerns, or othe	r concerns.	
pumped though 6" pipes h	our owner	Says tank	is for ald	for	
munholes, tanks over for	//				
6. Location of septage disposal:					