

DEPARTMENT OF PUBLIC HEALTH AND ENVIRONMENT

GOVERNMENT CENTER

14949 62nd STREET NORTH P.O. BOX 6 STILLWATER, MN 55082-0006 Office: 651-430-6655 TTY: 651-430-6246 FAX: 651-430-6730

Subsurface Sewage Treatment System Maintenance Permit

I IIIIS SECTION MUST be completed in its entirety	to constitute a v	alid		
This section must be completed in its entirety	in constitute a v	alid maintenance p	permit. This permit	must be completed
prior to performing maintenance activit	ies and remain or	n-site for the dura	tion of the maintena	nce activity.
Date of Maintenance: 121-16 Reason	for Maintenance:	104	tine	
Property Address: 145 St. Croix	TYS	Property Owner's N	Name: Jems	LLC
Municipality: <u>Lakeland</u> ZIP:550	Y3 Property Ide	entification Number	:	
Maintenance Permit No: \$469769 49	Naintainer Name a	nd License No. Pin	ky's Environmental S	ewer Service/L1673
Maintenance Performed	Tank Mea	surement (must be	completed if tanks	NOT pumped)
Tank(s) Pumped	Liquid Level of Tank in			
Sludge and scum measured	Sludge Level in Tank in Scum Level in Tank in			
Do tanks need to be pumped?	Sludge + Scum / Liquid Level X 100			
☐ Yes ☐ No (if no provide measurements)	II .		nks must be pumped	
 Access used to remove septage: Maintenant Were all covers securely replaced? Yes Is there evidence of tank leakage from a septent evidence of damaged, cracked, or structural 	□ No tic, holding, pret	reatment or pump	tank below the one	rating depth or
Tank	Leaking Out	Leaking In	Cover Damage	
Septic/Holding Tank #1	☐ Yes ☑ No	☐ Yes ☑ No	☐ Yes ☐ No	
Septic/Holding Tank #2	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
Pretreatment Tank	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
	_			
Pump Tank	☐ Yes ☐ No	Yes No	☐ Yes ☐ No	
4. How many gallons of septage were removed?	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	
4. How many gallons of septage were removed?				gal
-	gal Pretreatment	tankg	al Pump Tank	gal er concerns,